



Barnsdale Archery Mfg.  
100 East Antoine St  
Iron Mountain, MI 49801  
PH 906-774-1010  
FX 906-774-1705  
Email [davebarnsdale@gmail.com](mailto:davebarnsdale@gmail.com)  
4-8-16

Dear Customers,

It has come to my attention that the 8-32 x 1/2" screws I supplied with the ST cams to this date only have about 3 threads of engagement. This may, and in one case has, lead to the screws, or threads failing while being shot. This causes the module to fail. Although no one was hurt in this one incident, this could be a potentially dangerous situation.

Today, 4-8-16, I am sending out 8-32 x 5/8" screws to all my customers that have purchased a complete bow or a set of cams. Please replace the 1/2" screws with the new, 5/8" screws ASAP. If you replace them one at a time, there should be no need for a bow press. I would also recommend using blue thread locker when installing the new screws.

If you have purchased a bow through a dealer or private party, please contact me and I will get a set of screws out to you.

I regret this oversight on my part, I will endeavor to do better in the future.

Thank you for your continued support.

Sincerely,  
Dave Barnsdale